




MMP LA5-24V-40-A-100



PERFORMANCE CURVES:

The left graph shows Speed (in/s) on the y-axis (0.00 to 0.35) and Output Force (LBS) on the x-axis (0 to 1,000). The speed starts at approximately 0.33 in/s at 0 lbs and decreases linearly to about 0.29 in/s at 800 lbs.

Output Force (LBS)	Speed (in/s)
0	0.33
500	0.30
800	0.29

The right graph shows Current (A) on the y-axis (0 to 6) and Output Force (LBS) on the x-axis (0 to 1,000). The current starts at approximately 1.2 A at 0 lbs and increases linearly to about 5.5 A at 800 lbs.

Output Force (LBS)	Current (A)
0	1.2
500	4.0
800	5.5

MIDWEST MOTION PRODUCTS, INC.

www.midwestmotion.com

email: sales@midwestmotion.com